

# Misuratore di ESR a quattro punte

Off



On

Calibrazione	
1,00 mA	0,000 $\Omega$
0,90 mA	0,050 $\Omega$
0,80 mA	0,130 $\Omega$
0,70 mA	0,235 $\Omega$
0,60 mA	0,360 $\Omega$
0,50 mA	0,530 $\Omega$
0,40 mA	0,740 $\Omega$
0,30 mA	1,040 $\Omega$
0,20 mA	1,480 $\Omega$
0,10 mA	2,150 $\Omega$

Zero



Strumento  
1mA

